

# FACILITY COMPLIANCE INSPECTION REPORT

# Division of Waste Management Solid Waste Section

UNIT TYPE:											
Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Edgecombe				
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		PERMIT NO.: SLAS-33-06				
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		FILE TYPE: <b>COMPLIANCE</b>				

#### **FACILITY NAME AND ADDRESS:**

Blake Boswell Boswell & Son Septic Tank Service Inc. PO Box 236 Sharpsburg, NC 27878

**GPS COORDINATES**: <u>N</u>: 35.89958 <u>W</u>: -77.73565

#### **FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Blake Boswell

**Telephone:** 252-977-9384

Email address: blakebos@embarqmail.com

**Fax:** 252-977-9504

#### **FACILITY CONTACT ADDRESS:**

Same as above

**PARTICIPANTS**: Chester Cobb

**STATUS OF PERMIT**: Active **EXPIRES:** 10/11/2016

**PURPOSE OF SITE VISIT**: Routine

# STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous inspection conducted on 3/16/12.

# **OBSERVED VIOLATIONS:**

**NONE** 

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

#### FACILITY COMPLIANCE INSPECTION REPORT

# **Division of Waste Management Solid Waste Section**

Page 2 of 2

## **ADDITIONAL COMMENTS**

- 1. Signage present.
- 2. The path to the site is in excellent shape.
- 3. Markers present.
- 4. No discharges noticed outside of the permitted boundaries.
- 5. No spot dumps or thick application noticed.
- 6. Bermudagrass looked good. Site had been subsoiled earlier this year.
- 7. No application at time of inspection. pH not checked.
- 8. No objectionable odors noticed.
- 9. No change in any of the setbacks noticed.
- 10. Records not checked.
- 11. No violations noticed today.

Please contact me if you have any questions or concerns regarding this inspection report.

Chester R. Cobb

Phone: (919) 707-8283

Regional Representative

Sent on: 7/23/13		Email		Hand delivery	X	US Mail		Certified No. [_]
------------------	--	-------	--	---------------	---	---------	--	-------------------